Manual Supplement

Manual Title:	5730A Operators	Supplement Issue:	**1**
Print Date:	August 2013	Issue Date:	10/23
Revision/Date:	2, 7/23	Page Count:	2

This supplement contains information necessary to ensure the accuracy of the above manual.
This manual is distributed as an electronic manual online at www.flukecal.com.

© 2023 Fluke Corporation. All rights reserved.

FLUKE®
Calibration

Change #1, 347

For firmware version 2.0.9.0 and above:

On page A-15, under ***2500-Level Faults: Self Calibration***, at the end of the table, add:

2653	Could not Cal Wideband Frequency Ratio.

On page A-22, under ***3800-Level Faults: Self Diagnostics (Switch Matrix)***, at the end of the table, add:

3830	A8: K28 Relay Fault.
3831	A8: K21 Reset Relay Fault.
3832	A8: K12 & K2 Reset Relay Fault.
3833	A8: K21 Set Relay Fault.
3834	A8: K2 Set Relay Fault.
3835	A8: K12 Set Relay Fault.
3836	A8: BRF13/100 to RCL Fault.
3837	A8: K4 Set Relay Fault.
3838	A8: K6 Set Relay Fault.
3839	A8: K7 Set Relay Fault
3840	A8: K17 Reset Relay Fault.
3841	A8: K9, K13, & K14 Reset Relay Fault.
3842	A8: K9 & K14 Reset K13 Set Relay Fault.